

**SUMMARY SNAG LIST FOR 110KV TRANSMISSION LINES**

<b>Tower No./ Area</b>	<b>Snag</b>
7 - 8	Tree Cutting is stoped.
12 - 14	Tree Cutting is stoped.
14	Insulator Assembly Sets of Lien Chieu S/S side should be installed and will be installed at the VO No.1 Construction. ACSR, OPGW and GSW stringing work is not completed and will be installed at the VO No.1 Construction.
110kV Power Transition Yard	Painting for Fence Wall and Collumn is not completed.
	Termination Clamp of ACSR should be installed and will be installed after 110kV Cable Testing.
	Backfilling for around the Fence is not completed.
	Manhole Cover should be fixed.
	Latch Hole for Gate should be made.
	Earthing Inspection Chamber should be completed.